

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	3156	(power loss recovery) or "PLR"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	ADJ	ON	2006/05/10 09:51
L2	29	I1 with (coalesc\$3 or "fuse together" or together or fuse)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	ADJ	ON	2006/05/10 09:54
L3	4	I1: same (coalesc\$3 or "fuse together" or together or fuse) same (flash or eeprom or eprom or nonvolatile)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	ADJ	ON	2006/05/10 09:55
L4	30	I1 and (coalesc\$3 or "fuse together" or together or fuse) and (flash or eeprom or eprom or nonvolatile) and (ecc or (error correct\$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	ADJ	ON	2006/05/10 09:55